


Gloves > Sizing Chart

		GL220__	GL221__	GL222__	GL223__	GL224__
Size	Hand Measures	Lightweight	Heavyweight	Tactical	Rope Tech	Fingerless
XXS	circumference	N/A	N/A	N/A	Up to 7.5"	Up to 7.5"
	max length					7.0" - 7.5"
XS	circumference	7.0" - 7.5"	N/A	N/A	7.0" - 7.5"	
	max length	7.25"			7.25"	N/A
S	circumference	7.5" - 8.0"				
	max length	7.5"				N/A
M	circumference	8.0" - 8.75"				
	max length	7.75"				N/A
L	circumference	8.75" - 9.50"				
	max length	8.0"				N/A
XL	circumference	9.50" - 10.50"				
	max length	8.25"				N/A
XXL	circumference	10.50" - 12.0"				
	max length	8.50"				N/A

HOW TO MEASURE FOR SIZING OF PMI GLOVES:

- 1) Circumference: measure around knuckles.
- 2) Length: measure hand length from crease in wrist to tip of 3rd/longest finger.
- 3) If hand length exceeds the maximum pick next larger size of glove.



Pigeon Mountain Industries, Inc.
PO Box 803
LaFayette, GA 30728

T: 800.282.7673
F: 706.764.1437
E: custserv@pmirope.com
W: www.pmirope.com